

	Type	Hits	Search Text	DBs
1	BRS	15	4,000,483	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	11	5,864,458	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	5	5,864,458 and transformer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	41	("3241026"   "3249810"   "3488761"   "4070641"   "4071836"   "4237441"   "4238812"   "4315237"   "4317027"   "4426633"   "4445079"   "4485283"   "4545926"   "4574229"   "4583146"   "4689475"   "4724417"   "4724504"   "4774024"   "4780598"   "4800253"   "4808965"   "4816958"   "4845838"   "4857880"   "4859836"   "4901186"   "4907340"   "4910631"   "4924074"   "4935156"   "4967176"   "5023744"   "5049850"   "5089801"   "5254816"   "5296996"   "5378407"   "5379176"   "5428195"   "5493101") .PN.	USPAT
5	BRS	9	5864458.URPN.	USPAT

	Time Stamp	Comments	Error Definition	Errors
1	2003/12/02 14:23			0
2	2003/12/01 14:00			0
3	2003/12/01 14:58			0
4	2003/12/01 14:11			0
5	2003/12/01 14:19			0

	Type	Hits	Search Text	DBs
6	BRS	49	("D297928"   "D328057"   "3354271"   "3518524"   "3609457"   "3757194"   "3928792"   "4084123"   "4118615"   "4240022"   "4241285"   "4266257"   "4335414"   "4415959"   "4430681"   "4441146"   "4507368"   "4528492"   "4648020"   "4675797"   "4712055"   "4827104"   "4873453"   "4926106"   "5013993"   "5095259"   "5144217"   "5208525"   "5217395"   "5278747"   "5293098"   "5453904"   "5483437"   "5497245"   "5602455"   "5629602"   "5633096"   "5645746"   "5715156"   "5721481"   "5731683"   "5783927"   "5801513"   "5805068"   "5814947"   "5834903"   "5847541"   "5864458"   "5973605") .PN.	USPAT
7	BRS	7	3,631,322	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
8	BRS	13	5,667,711	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	175	4,177,376	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
10	BRS	17	5,028,216	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	9	5,493,101	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	5	4,810,991	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	1	4810991.URPN.	USPAT
14	BRS	5	6,243,276	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
6	2003/12/01 14:38			0
7	2003/12/01 14:59			0
8	2003/12/01 14:59			0
9	2003/12/01 15:00			0
10	2003/12/01 15:06			0
11	2003/12/01 15:18			0
12	2003/12/01 15:29			0
13	2003/12/01 15:19			0
14	2003/12/01 16:00			0

	Type	Hits	Search Text	DBs
15	BRS	49	("D297928"   "D328057"   "3354271"   "3518524"   "3609457"   "3757194"   "3928792"   "4084123"   "4118615"   "4240022"   "4241285"   "4266257"   "4335414"   "4415959"   "4430681"   "4441146"   "4507368"   "4528492"   "4648020"   "4675797"   "4712055"   "4827104"   "4873453"   "4926106"   "5013993"   "5095259"   "5144217"   "5208525"   "5217395"   "5278747"   "5293098"   "5453904"   "5483437"   "5497245"   "5602455"   "5629602"   "5633096"   "5645746"   "5715156"   "5721481"   "5731683"   "5783927"   "5801513"   "5805068"   "5814947"   "5834903"   "5847541"   "5864458"   "5973605").PN.	USPAT
16	BRS	1	ptc adj mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	390	ptc same mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
18	BRS	80	ptc same mounting and distance	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	11	ptc same mounting same distance	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	56	ptc same distance and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	2	ptc adj2 distance and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
22	BRS	3	ptc adj3 distance and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	11	ptc near3 distance and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	2	ptc same (protecting protection) same distance and mounting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
15	2003/12/01 15:30			0
16	2003/12/01 16:02			0
17	2003/12/01 16:02			0
18	2003/12/01 16:03			0
19	2003/12/01 16:15			0
20	2003/12/01 16:16			0
21	2003/12/01 16:16			0
22	2003/12/01 16:16			0
23	2003/12/01 16:19			0
24	2003/12/01 16:32			0

	Type	Hits	Search Text	DBs
25	BRS	1781	361/212	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	341	361/37	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	290	361/38	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	1613	ptc same (polymeric polymer)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	49	ptc same (polymeric polymer) and transformer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	11	ptc same (polymeric polymer) and transformer same protection	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
31	BRS	307	transformer and Nema	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
32	BRS	17	transformer and Nema adj class	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	5727	transformer and VA	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	6	transformer and "75" adj VA	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
35	BRS	15	transformer and non adj energy	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
36	BRS	4	4,951,168	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
37	BRS	5	("2776855"   "3532934"   "3611034"   "3700965"   "4053938").PN.	USPAT
38	BRS	2	4951168.URPN.	USPAT
39	BRS	161	361/836	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
40	BRS	56	5,174,924	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
41	BRS	2	"1961120"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
42	BRS	247	Non-energy	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
25	2003/12/01 16:33			0
26	2003/12/01 16:34			0
27	2003/12/02 09:37			0
28	2003/12/02 14:24			0
29	2003/12/02 14:24			0
30	2003/12/02 14:24			0
31	2003/12/02 14:24			0
32	2003/12/02 14:25			0
33	2003/12/02 14:25			0
34	2003/12/02 14:25			0
35	2003/12/02 14:26			0
36	2003/12/02 14:26			0
37	2003/12/02 14:26			0
38	2003/12/02 14:26			0
39	2003/12/02 14:27			0
40	2003/12/03 08:54			0
41	2003/12/03 08:54			0
42	2003/12/03 08:55			0



	Type	Hits	Search Text	DBs
43	BRS	2	Non-energy adj limiting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
44	BRS	259	ptc same transformer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
45	BRS	0	ptc same transformer adj protection	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
46	BRS	2	ptc and transformer adj protection	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
47	BRS	2	ptc and crimp adj joint	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
48	BRS	104	ptc and crimp	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
49	BRS	19	ptc same crimp	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
50	BRS	1589	ptc same ceramic	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
51	BRS	810	ptc same ceramic and advantage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
52	BRS	122	ptc same ceramic same advantage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
53	BRS	41	ptc near ceramic same advantage	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
54	BRS	1	ptc near ceramic same advantage and transformer	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
55	BRS	3267	heatsink	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
56	BRS	2001	heatsink and thermal	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
57	BRS	232	heatsink and thermal adj conduction	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
58	BRS	94	heatsink same thermal adj conduction	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
59	BRS	509	165/80.1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
60	BRS	3	4,951,168	USPAT; US-PGPUB

	Time Stamp	Comments	Error Definition	Errors
43	2003/12/03 08:55			0
44	2003/12/03 08:55			0
45	2003/12/03 08:56			0
46	2003/12/03 08:56			0
47	2003/12/03 08:56			0
48	2003/12/03 08:57			0
49	2003/12/03 08:57			0
50	2003/12/03 08:57			0
51	2003/12/03 08:57			0
52	2003/12/03 08:57			0
53	2003/12/03 08:58			0
54	2003/12/03 09:18			0
55	2003/12/03 09:18			0
56	2003/12/03 09:19			0
57	2003/12/03 09:19			0
58	2003/12/03 09:25			0
59	2003/12/03 09:25			0
60	2003/12/03 10:06			0

	Type	Hits	Search Text	DBs
61	BRS	1427	165/80.2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
62	BRS	10836	transformer adj winding	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
63	BRS	856	transformer adj winding same (wire wires)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
64	BRS	1	transformer adj winding same (wire wires) same (thick thickness) and 0.25 adj mm	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
65	BRS	0	transformer same (wire wires) same isolation same (thick thickness) and 0.25 adj mm	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
66	BRS	0	transformer and (wire wires) same isolation same (thick thickness) and 0.25 adj mm	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
67	BRS	61	transformer and (wire wires) same isolation same (thick thickness)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
68	BRS	13733	ptc	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
69	BRS	0	ptc and current adj ampers	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
70	BRS	26	ptc and current adj A	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
71	BRS	3	ptc and current adj A and voltage adj V	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
72	BRS	72	ptc and current adj2 A and voltage adj2 V	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
73	BRS	49	ptc and current near A and voltage near V	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
74	BRS	4312	165/185	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
75	BRS	418	transformer and plastic adj cover	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
76	BRS	44	transformer same plastic adj cover	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
77	BRS	2	Non adj energy adj limiting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
61	2003/12/03 10:58			0
62	2003/12/03 14:46			0
63	2003/12/03 14:46			0
64	2003/12/03 14:47			0
65	2003/12/03 14:48			0
66	2003/12/03 14:48			0
67	2003/12/03 14:49			0
68	2003/12/03 14:49			0
69	2003/12/03 14:49			0
70	2003/12/03 14:50			0
71	2003/12/03 14:50			0
72	2003/12/03 14:50			0
73	2003/12/03 14:51			0
74	2003/12/03 14:51			0
75	2003/12/04 08:54			0
76	2003/12/04 08:54			0
77	2003/12/04 08:55			0